# ROCKY FLATS ENVIRONMENTAL TECHNOLOGY SITE ENVIRONMENTAL RESTORATION CONSULTATIVE PROCESS RECORD

Date/Time:

May 30, 2002

**Site Contact(s):** 

Susan Serreze, Annette Primrose

Phone:

303-966-2677, 303-966-4385

Regulatory Contact: Elizabeth Pottorff, CDPHE, David Kruchek, CDPHE,

Gary

Kleeman, EPA

Phone:

303-692-3429, 303-692-3328, 303-312-6246

Agency:

**CDPHE** 

Purpose of Contact: Notifications #02-04 and #02-07 Consultative Process Discussion

## Discussion

A meeting was held with Elizabeth Pottorff (CDPHE), David Kruchek (CDPHE) and Gary Kleeman (EPA) to discuss CDPHE comments on Notification #02-04 and to begin the consultative process discussion for Notification #02-07 Several issues were resolved and include the following

Notification to the agencies of the removal of additional slabs not covered by an ER RSOP notification will be through a Consultative Process Record

#### Notification #02-04

- The boundary of IHSS Group 600-1 was originally intended to include B662 (reference 1992 HRR) The boundary will be changed on Figure 4 in Notification #02-04 and text will be added to the Notification to include B662
- Sampling locations for the B662 area will be based on the extension of the existing statistical grid for IHSS Group 600-1 (IASAP Addendum #IA-02-01) Agreement will be reached on these sampling locations and any additional biased sampling locations through the consultative process

## Notification #02-07

Two concrete slabs are present in IHSS Group 600-2 The location of the slabs is being surveyed Concern was expressed by CDPHE that parts of the slabs may be covered by gravel



CEX-105-01



- Several groundwater wells were evaluated to determine if analytical results indicated exceedances of RFCA ALs No exceedances were noted
- One surface water sampling location was found in this IHSS Group Analytical results indicated that metals exceeded ALs The location of the sample could not be correlated with current surface water features
- Additional information about IHSS Group 600-2 indicated that depleted uranium may have been stored in PCB oil PCB analysis was added to seven sampling locations in IASAP Addendum #IA-02-06

Administrative Record

# Required Distribution

L Norland, K-H

C Spreng, CDPHE D Foss, CH2MH D Kruchek, CDPHE S Serreze, Arcadia E Pottorff, CDPHE C Madore, RMC G Kleeman, EPA M Burmeister, RMC N Castaneda, RFFO C Cowdery, Washington Group S Luker, RMC L Brooks, K-H M Broussard, K-H S Paris, RMC L Butler, K-H D Reeder, Summit D Strand, Alpha A Primrose, K-H ER Meeting Minutes Book S Nesta, K-H



2/2